Site Name:		Operation						Region 6		
Task Order 62 CES Environ	Date: 5-7-2015 Division/			DAILY WORK ORDER						
ranch: Federal Group: Response						Emergency and Rapid Response Service				
WORK AUTHORIZED:			denending (n roinfall						
Continue to pump water on si										
Continue development of prof Continue removal of water, oi	l cludge	and wa	eta from the	ASTs Frac Tanks	Tote	s and	Drums			
Site Cerclis:# TXD 008	On-Scene Coordinator:			E	ERRS Response Manager					
Contract Number: EP - S6 - 07 -02		Gary Moore, USEPA			Le	LeRoy Cassidey, CB&I Federal				
Task Order: 062		Date: 5.7.2015				ate: 5.	5.7.2015 Time: 1700			
PERSONNEL ON-SITE:	QTY	Used	Unused	EQUIPMENT ON SITE:	-		QTY	USED	Unused	
Response Manager	1	1		Pick -up	o Truc	k	2	2		
Foreman	1	1		Generato Trash Pump		or	2	2		
Equipment Operator	0	0				os	0	0		
Truck Driver	0	0				er	1	1		
Laborer	2	2		Frac Tank w L			1	1		
Health and Safety Manager	0	0			4,000 PSI Pressure Washe			1		
PERSONNEL OFF-SITE			U-1	Open Top F			5	5		
Subcontract Manager	1	1		Vacuum Truck Air Mover			1	1		
	1	1		Carbon Vapor Unit			1	1		
Transport and Disposal Coord				Skid Steer						
Field Cost Accountant	1	1 - 30 - 10 - 10 - 10 - 10 - 10 - 10 - 1				1	1			
				Vacuum/OT Boxe			14	14		
					9,000 lb Overhead Lif		1	1 1		
				Storage			1	1		
				Myers (Bean) Pur		1	1	1	V-02	
				Air Com	press	or	1	1		
WORK ACCOMPLISHED /	MENDA	ENTS (non, V	Innut &	ordovio 1 O	00 5Pon5):		
WORK ACCOMPLISHED / A										
The RM continued processing Manifest/LDR for US Ecology	g of oper	rational-h	H/Safety pap	erwork, procuremen	its, ar	nd inv	oices. Pri	epared		
T&D Coordinator continued p Harbors.								itrite bag, v	with Clean	
The crew helped Triad Trans washed the poly tote. They co	port load	their tar	nker with wa	ste for 4048 (PT3).	The o	crew o	cut a hole shouse tre	and press	ure	
	Date:			000	>	-	7		T	
osc			Time:	RMS	نالية	Die	Date: 5.8.	2015	Time:1000	
							0			
Next OPERATIONAL PERIO	DD (admin	istrative, ta	actical / status	changes, special instruction	ions, H	i&S)(In	put for next	DWO):		
Continue sump cleaning and warehouse. Prepare and ship				drums and totes. Ren	nove	d deb	ris from tr	enches in	the	
Continue to sample, profile, a up procurements and track c		dule was	ste for final t	ransportation and dis	sposa	al. Co	ontinue to	process in	voices, set	